

# WELL STATUS REPORT

(To be submitted in quintuplicate on all inactive wells)

NAME AND ADDRESS OF OPERATOR

Atlantic Richfield Company, P. O. Box 1710, Hobbs, New Mexico 88240

WELL NO. AND LEASE NAME

Turner "B" #76

FRAME NO.

LC 82933

RECEIVED

COUNTY

Eddy

STATE

N. M.

30

Footage Location

660

feet from

South

660

feet from

East

Pool

Grayburg Jackson

1. When Was Well Shut-in or Last Produced?

APR 7 1977

July, 1975

2. Type Well

O. G. C.  
ARTESIA, OFFICE

☐ Oil Well ☐ Gas Well ☒ Temp. Abd. Well ☒ Water Injection Wells

3. Producing Capability

BOPD \_\_\_\_\_ MCFGPD \_\_\_\_\_

BWPD \_\_\_\_\_ Date Last Tested \_\_\_\_\_

4. Is Well Considered Capable of Production in Paying Quantities?

☐ Yes

☐ No

5. If Capable of Producing in Paying Quantities, Give Reasons For Not Producing Well.

6. If Not Capable of Producing in Paying Quantities, Give Reasons For Not Plugging Well at This Time.

7. What Are Future Plans For Operating Well (Include Estimated Dates)?

Well under study to return to service during 4th Qtr 1977.

RECEIVED

APR 04 1977

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Sr. Dist. Prod. Supv.

DATE 3-30-77

(This space for Federal or State office use)

APPROVED BY [Signature]

TITLE ACTING DISTRICT ENGINEER

DATE APR 6 1977

CONDITIONS OF APPROVAL, IF ANY: