



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. NE - 0933

Unit 1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

*Stagner* November 21, 1956  
Well No. 1 is located 1900 ft. from NU line and 1900 ft. from E line of sec. 11  
11 (1/4 Sec. and Sec. No.) 11 (Twp.) 11 (Range) 11 (Meridian)  
Wilcox (Field) Wilcox (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is about 3710 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to re-enter this abandoned well cleaning out to a depth of approximately 3850' with cable tools and will attempt to re-complete at this depth. Respect testing will be the Livingston Sand to 3850'. Plan to tie into a 5/8" casing 21/2' test, bottomed at 670' and 3850' 5/8" casing 11/2' test. Cement at 670' and at 3850' with 100 gr.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Ernest A. Hansen

Address Formerly P.B. English

Lawrence, New Mexico

By Ernest A. Hansen  
Title Operator