



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **70133**
Unit **Ginsberg**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 22, 1953

Well No. **2** is located **660** ft. from **xxN** line and **660** ft. from **E** line of sec. **8**
SE 1/4 SE 1/4 **18S** **31E** **N.M.P.M.**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Shugart **Eddy** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was re-entered with cable tools, drilled to 3185', set 7" casing to approximately 550' and set with 50 sz. cement, ran 4 1/2" casing in 7" stub at 1750' and set with 100sz. cement. Treated w/Western Company 21000 bbls. water, 19,000 lbs. sand 20-40 or 40-60 mesh. Pumped for 30 days. Well pumped 1 bbl. per day, and is temporarily abandoned.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **R.D. Collier**

Address **P.O. Box 798**

Artesia, New Mexico

By **R.D. Collier**

Title **Production Clerk**