

Indian Agency.....

(SUBMIT IN TRIPLICATE)

U. S. Land Office Las CrucesLease or permit No. 028465

Allottee.....

Lease No.....

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL..... X	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sept. 14, 1939

Well No. 2 is located 990 ft. from N line and 330 ft. from Ex line of sec. 4SW of NW of NE Sec. 4 18 S 29 E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Loco Hills Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 3552 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Because of tools lost at 2405 feet we wish to plug this hole, in accordance with Government specifications, and skid rig 50 feet east and drill a second well. Bottom to be cemented, mud back to 900 feet, cement plug set to 850 feet and mud to surface, cellar and pit filled and marker set.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company UNDERWOOD & SANDERSAddress Artesia, New MexicoBy W.B. MarshallTitle Superintendent