



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 028772(b)
Unit Dunn

30-015-06114

Copy

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

..... March 3, 1956.

Well No. 11-Dunn is located 1950 ft. from {N} line and 1930 ft. from {E} line of sec. 10
(formerly #3 well) {S}

SE 1/4 sec. 10 T. 18 S. R. 28 E. N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Artesia Pool Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well drilled by Flynn Welch & Yates in 1926 to 2419'. Will re-enter and deepen to top of San Andres at about 2520'. Will set 4 1/2" csg on top of pay and cc w/100 sacks, then frac lowermost Grayburg san.

Old Permit #Roswell 052122

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Resler & Yates, et al
(formerly Malco-Resler-Yates)
Address 304 Carper Bldg.
Artesia, New Mexico

By /s/ Vilas Sheldon

Title