

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED
FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS MAY 9 1960

(Submit to appropriate District Office as per Commission Rule 1104) D. C. C.

Name of Company Graridge Corporation		Address Box 752, Breckenridge, Texas					
Lease Resler Yates State	Well No. 307	Unit Letter H	Section 28	Township 18S	Range 28E		
Date Work Performed See Below	Pool Artesia	County Eddy					

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☐ Remedial Work Sandfrac

Detailed account of work done, nature and quantity of materials used, and results obtained.

4-16-60 Sandfrac'd formation thru perforations 2102'-22' with 3000 gallons
Hyflo, 250 gallons 15% NE acid, 5000# 20-40 sand, and 1500# 10-20
sand, Maximum Pressure 3500#, Minimum 1600#. Average injection
rate 20.5 BPM

4-19-60 Moved in & rigged up B & S Pulling Unit.

4-20-60 Sand pumped well clean. Ran tubing & rods and put well back on
pump.

Witnessed by Paul Darnell	Position Superintendent	Company Graridge Corporation
------------------------------	----------------------------	---------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPT	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete
to the best of my knowledge.

Approved by <i>M L Armstrong</i>	Name <i>Charles W. Smith</i>
Title OIL AND GAS INSPECTOR	Position Production Clerk
Date MAY 9 1960	Company Graridge Corporation

COMMISSIONER	
OFFICE	
JAN 10 1908	
RECEIVED	
FILED	
BUREAU OF MINES	