

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1706)

Name of Company Granridge Corporation			Address Box 752, Breckenridge, Texas			
Lease Resler Yates State	Well No. 383	Unit Letter G	Section 28	Township 18S	Range 28E	
Date Work Performed 10-20-59	Pool Artesia		County Eddy			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☒ Other (Explain):
☐ Plugging ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Ran formation and collar logs. Perforated 5 1/2" casing from 2052' to 2072' with 4 bullets per foot. Total of 88 holes.

Witnessed by Paul Darnell	Position Superintendent	Company Granridge Corporation
------------------------------	----------------------------	----------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>M L Armstrong</i>	Name <i>Charles W. Smith</i>
Title <i>Superintendent</i>	Position Charles W. Smith Production Clerk
Date <i>Nov 10 1959</i>	Company Granridge Corporation

4

2

1

✓