

Form 9-281a
(Feb. 1961)

(SUBMIT IN TRIPLICATE)

Land Office _____

Lease No. **84-0962-A**

Unit **0**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

APPROVED
NOV 15 1963
ACTING DISTRICT

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 8, 1963

Well No. **1** is located **660** ft. from **{N}** line and **660** ft. from **{E}** line of sec. **7**

1/4 **1/4** **Sec. 7** **13N** **31E** **104M**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat **Edley** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5566.2** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On November 7, 1963, ran 703' of used J-55, 8 rd. 15 lb., 8 5/8" csg. Cemented with 50 sacks. Waited 24 hours. Tested no fluid.

Denton Oil Well Cementing Company performed the job.

RECEIVED
NOV 18 1963
O. C. C.
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Jack L. McClellan**

Address **Box 848**

Roswell, New Mexico

By **Jack L. McClellan**

Title **Operator**