

(SUBMIT IN TRIPLICATE)

## UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4. Form Approved.				
ist !	Lease No. LC 063621			
RIOR	Unit R			
VIOIX	Unit RECEIVES			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALIER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		Arten	la, H. X.	1-31 19 63	
#ston Federal Well No. 1 is locate	ed 1650ft.	from $\left\{ \begin{array}{l} \mathbf{N} \\ \mathbf{S} \end{array} \right\}$ line	and 990 tt. from	line of sec7	
NE SE Sec. 7	<b>1</b> 3 5	30 €	HEPR		
(1/4 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
Loco Wills Under.	24 <b>45</b>		No.	Nev Mexico	
(Field)	(County or Subdivision)		(State	or Territory)	
<b>31.</b>					

The elevation of the derrick floor above sea level is 3523ft.

## **DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We ran 2870 feet of 5 1/2" casing in this well and cemented with 150 sacks. After waiting for the esment to set we drilled the plu the plus and tests showed complete water shutoff. Drilling was continued.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company	CAP Ortlling Commany			
Address	30x 375	MA (1)		
	Artesia, S. P.	By My Holmer		
••••••		Title		