

Land Office **Las Cruces**Lease No. **025978 - B**

Unit _____

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of 3 5/8" csg.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

McClay ✓

November 7, 1963

Well No. **5** is located **1650** ft. from **[N]** line and **330** ft. from **[E]** line of sec. **33****SE 1/4** **33** **18S** **30E** **NMPM**

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

No. **Denson****Eddy****New Mexico**

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 559' of 3 5/8" csg and cemented with 50 sx.

Ran 20 sx. mud before cementing.

Ran 3219' new 5 1/2" csg and mudded with 25 sx. of Jet and cemented with 100 sx. cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Simms & Reese Oil Company**Address **200 Booker Building****Artesia, New Mexico**

By

*Robert R. Spruance*Title **Partner**