

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRORATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Kersey & Company		Address Box 316, Artesia, New Mexico			
Lease Twin Lakes	Well No. 15	Unit Letter N	Section 28	Township 18S	Range 28E
Date Work Performed	Pool Artesia		County Eddy		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
☐ Plugging
 ☐ Remedial Work
 Fracturing

Detailed account of work done, nature and quantity of materials used, and results obtained.

Perforated 2016-2029' with 2 shots/foot. Fractured with water. 8500 gallons, 8500# 20-40 sand. Formation broke at 3200#. Average treating pressure 2000#

RECEIVED

FEB 19 1963

Witnessed by Harold Kersey	Position Partner	Company Kersey & Company
--------------------------------------	----------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D 2083'	P B T D 2074'	Producing Interval 2016 - 2029	Completion Date Feb. 2, 1963
Tubing Diameter 2 3/8	Tubing Depth 2005	Oil String Diameter 5 1/2	Oil String Depth 2074'	
Perforated Interval(s) 2016 - 2029'				
Open Hole Interval None		Producing Formation(s) 1st zone grayburg		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by

M. L. Armstrong

Name

Harold Kersey

Title

OIL AND GAS INSPECTOR

Position

Partner

Date

FEB 19 1963

Company

Kersey & Company