

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Las Cruces  
Lease No. 028975 b  
Unit I

RECEIVED

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	Sub. report of 8 5/8" csg.	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

McClay

Well No. 6x is located 2310 ft. from N line and 348 ft. from E line of sec. 33NE 34 (1/4 Sec. and Sec. No.) 33 188 (Twp.) 30E (Range) MRPM (Meridian)North Benson (Field) Eddy (County or Subdivision) New Mexico (Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 560' of 8 5/8" csg. Set @ 571' - Cemented w/ 50 sz. - 3 sz. jel &amp; 1 sz Calcium Chloride.

Plugged down @ 10:00 AM 11/8/63

11/9/63 Orig plug tested 1 hr.

RECEIVED  
DEC 9 1963  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Simms & Reese Oil CompanyAddress 200 Booker BuildingArtesia, New MexicoBy R. L. HeinsohTitle Partner