

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 028978-6

Unit

copy 3?

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

ILLEGIBLE

MARK NATURE OF REPORT, NOTICE, OR OTHER DATA

Dec. 9

1963

Well No. 6X is located 2310 ft. from S line and 348 ft. from E line of sec. 33

NE 33 (1/4 Sec. and Sec. No.) 33 18 (Twp.) 30 (Range) W1PM (Meridian)

North Benson (Field) Eddy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We plan to plug this well in the following manner per instructions of Mr. Shuok. Cement plugs as follows:

3000 - 3100, 2750 - 2850, 1450 - 1550, 521 - 621 and placed between plugs - cement cellar and set markers.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Simms & Reese Oil Company

Address 200 Booker Building

Artesia, New Mexico

By

R. L. Heinzel

Title

Partner