DEPARTMENT OF THE INTERIOR T ENGINEER

(SUBMIT IN TRIPLICATE

GEOLOGICAL SURVEY

UNITED STATES

Budget Bureau No. 42-R358.4. Form Approved.

Land Office Las Cruces Lesse No. 0 28978 b

Unit _____

| SUNDRY NOTICES AND REPORTS ON WELLS | |
|--|---|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF ABANDONMENT. |
| (INDICATE ABOVE BY CHECK MARK NAT | URE OF REPORT, NOTICE, OR OTHER DATA) |
| Well No. 6X is located 2310 ft. from Well No. 6X | Solution State of Territory State of Territo |
| The elevation of the derrick floor above sea level | is ft. |
| DETAILS OF WORK (State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement- | |
| Cemented Plugs as follows: 2000 - 2100, 2750 - 2850, 1450 - between plugs - cemented cellar | important proposed work) |
| ILLECIBL | JAN 1 4 SURVO |
| | ng by the Geological Survey before operations may be commenced. |
| Company Simma & Reese Oil Company | |
| Artesia, New Mexico | By P. f. Hernsol |

Title Partner