

NUMBER OF COPIES RECEIVED		3
DISTRIBUTION		
SANTA FE		
FILE	1	
U.S.G.S.		
LAND OFFICE		
TRANSPORTER	OIL	
	GAS	
PRODUCTION OFFICE		
OPERATOR	1	

# NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Cima Capitan, Inc. (N.S.I.)				Address P.O. Drawer 1343, Artesia, N.M.			
Lease Adkins Williams		Well No. 7	Unit Letter P2	Section 17	Township 18S	Range 28E	
Date Work Performed Aug. 11, 1963		Pool Artesia			County Eddy		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain):
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Ran 550.75' - 8 5/8" 24# Casing and mudded. Bailed hole dry and tested 1 hr. hole dry.

RECEIVED

OCT 1 1963

O. C. C.  
ARTESIA, OFFICE

Witnessed by Thomas F. Welch	Position V. Pres.	Company Cima Capitan, Inc. (N.S.I.)
---------------------------------	----------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

### ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

### RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>M. J. Armstrong</i>	Name <i>Louis C. Baker</i>
Title Oil Well Inspector	Position Secretary-Treasurer
Date MAR 18 1964	Company Cima Capitan, Inc. (N.S.I.)