

Form 9-581
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe, N.M.
 Lease No. 11 049904
 Unit _____
 Saunders "A"

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Artesia, New Mexico

November 23, 1959

Well No. 196 is located 20.10 ft. from $\begin{matrix} N \\ S \end{matrix}$ line and 90 ft. from $\begin{matrix} E \\ W \end{matrix}$ line of sec. 12

NW¹/4SW¹ Sec. 12 18 S. 20 E. N.M.P.M.
(S. Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Loco Hills	Eddy	New Mexico
(Field)	(County or Subdivision)	(State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 14 joints (424') 7 5/8" 24w J55 casing, set at 436', KB
and cemented with 50 sacks cement, plus 8# salt per sack and
2% calcium Chloride. Left 30' cement in pipe. Plugged down
@ 4:10 A. M., November 27, 1963.

After standing 18 hours, tested blow out preventer and casing @ 600psi for 30 minutes. No pressure reduction.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BLANCH & YATES LIL COMPANY

Address 321 Carper Building

Artesia, New Mexico

By

Title Bookkeeper