			ر س <del>ر المراجعة ( المراجعة (</del>				
UNITED STATES UNITED STATES DEPARTMENT OF THE INTE GEOLOGICAL SURVEY		SUBMIT IN TRIPLICATE (Other instructions on r verse side)	5. LEASE DESIGNATION	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. LC 028772 (A)			
Do not use t	<b>JNDRY NC</b> this form for pre- Use "APPI	PTICES AND REPORTS oposals to drill or to deepen or phy ICATION FOR PERMIT for suc	DON WELLS	6. IF INDIAN, ALLOTTI	EE OR TRIBE NAME		
1. OIL CAS WELL COTHER WELL WELL COTHER 2. NAME OF OPERATOR			JAN 28-1980	7. UNIT AGREEMENT NAME Ballard Grayburg San Andres Unit S. FARM OR LEASE NAME			
Anadarko	Productio	Tract No. 1 9. WELL NO.					
P. O. Boo 1. normon of whith See also space 17 At surface	(Report location helow, )		ny State requirements. • 7, T18S, R29E nty, New Mexico	Graybur 11. SEC., T., R., M., OR SURVEY OR ARE	11 <b>s</b> Queen g San Andres BLE, AND		
14. PERMIC NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>3601 GL</b>		12. COUNTY OR PARIS			
 16.	Check NOTICE OF IN	Appropriate Box To Indicate	Nature of Notice, Report, or	Other Data	New Mexico		
TEST WATER SHU FRACTURE TREAT SHOOT OR ACIDIZI	X	PULL OR ALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR - 502155	REPAIRING ALTERING ABANDONMA	TANING		
Generatic write		CHANGE PLANS	(Other) (Note: Report result Completion or Recom	ts of multiple completion pletion Report and Log fo	of multiple completion on Well tion Report and Log form.)		
17. DESCRIBE PROPOSE proposed work, neut to this wor	It well is dire	OPERATIONS (Clearly state all perti- ectionally drilled, give subsurface le	nent details, and give pertinent date ocations and measured and true verti	s, including estimated da cal depths for all marker	te of starting any is and zones perti-		

- 1. Rigged up pulling unit, pulled rods and tubing and set packer @ 2390'
- 2. Fraced all Grayburg Zones in 5 equal stages, each stage consisting of 15,000 gals of RF-30, 250 gals of 15% NE acid, 6,000# 100 mesh sand, 8,500# 20/40 sand, 3,000# 10/20 sand & 33 gals of United Scale preventor. Each stage was separated by a block composed of moth balls and rock salt. Average frac rate = 27 BPM @ 3000#.
- 3. Pulled packer, re-ran tubing, bottom-hole pump and rods and returned well to production.

15. I hereby certify that the foregoing is true and forrect SIGNED All Studies Strengthe	Area Supervisor	DATE _	October	2, 1979
APPROVED BY LAY 2 CONVITIONS OF APPROVAL, IF ANY:	ACTIVIC DISTRUCT PRAVILLER TITLE	DATE _	<b>CCT</b> ? <sup>1</sup>	ş7 <b>9</b>