

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office **Las Cruces**
Lease No. **028978 b**
Unit **C**

GUNDY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	Subsequent Report of Cementing Surface Casing X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 31, 1964

McClay

7

Well No. 7 is located 330 ft. from {N} line and 1650 ft. from {E} line of sec. 33

NW 1/4 NW 1/4

33

18S

30E

NMPM

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

North Benson

Bddy

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 3442 ft. ~~3440~~

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 8 5/8" - 573' - mudded with 4 sz. jel, 50 sz. Cement, 1 sz. Calcium Chloride.

ILLEGIBLE
RECEIVED
APR 6 1964
O. C. C.
ARTESIA, OFFICERECEIVED
APR 6 1964
U. S. G. S.
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Simms & Moore Oil Company**Address **200 Becker Building****Artesia, New Mexico**

By

Title **Partner**