

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals for new wells or for existing wells in different reservoirs. Use Form 9-331-A for such purposes.)

RECEIVED

1. oil well ☐ gas well ☐ other ☐ **FEB 10 1983**
2. NAME OF OPERATOR
Yates Drilling Co. **O. C. D.**
3. ADDRESS OF OPERATOR
207 S. 4th St., Artesia, NM 88210 **ARTESIA OFFICE**
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660 FNL & 1080 FNL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: ☐ SUBSEQUENT REPORT OF:
TEST WATER SHUT OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETION ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Replug well. NEW D. Order No. R-7012

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Replugged well as follows: Cleaned out to 2605' w/7-7/8" bit. Set 100 sx Class "C" cement plug at 2508'. Tagged plug at 2718'. Set 100 sx Class "C" 3% CaCl plug at 2508'. Tagged plug at 2150'. Set 75 sx Class "C" w/3% CaCl cement plug at 1000'. Tagged plug at 740'. Set 15 sx surface plug. Installed dry hole marker. Witnessed by Mr. Mike Williams, OCD, Artesia.

Work started 10-12-82
Work Completed 10-14-82

Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED W. L. Williams TITLE Engineering Secty DATE 10-18-82

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL IF ANY

TITLE

DATE