

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	/
U.S.G.S.	/
LAND OFFICE	
OPERATOR	/

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION
DEC 26 1978

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		5a. Indicate Type of Lease State <input type="checkbox"/> <u>7.1</u> <input checked="" type="checkbox"/> <u>7.2</u>
2. Name of Operator <u>Yates Petroleum Corporation</u> ✓		5. State Oil & Gas Lease No.
3. Address of Operator <u>207 S. 4th Street, Artesia, New Mexico 88210</u>		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>A</u> <u>990</u> FEET FROM THE <u>FNL</u> LINE AND <u>330</u> FEET FROM THE <u>FEL</u> LINE, SECTION <u>25</u> TOWNSHIP <u>18</u> RANGE <u>30</u> NMPM.		8. Farm or Lease Name <u>Creek AL</u>
		9. Well No. <u>1</u> <u>1</u>
		10. Field and Pool, or Wildcat <u>Shugart (Seven Rivers)</u>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <u>Eddy</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

December 15, 1978

The cellar of the subject well was dug out and the outlet of the braden head was exposed. One opening from the braden head was connected to a second valve at the surface. All connections and fittings are high pressure as outlined in OCC Rule 115. The well was inspected by Mr. Mike Williams, OCC Field Supervisor.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Superintendent DATE 12/18/78

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE DEC 27 1978

CONDITIONS OF APPROVAL, IF ANY: