

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-8186
7. Unit Agreement Name
8. Farm or Lease Name Marathon "AM State Gas Co."
9. Well No. 1
10. Field and Pool, or Wildcat Atoka-Penn
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Yates Petroleum Corporation
3. Address of Operator 207 South 4th Street, Artesia, New Mexico 88210
4. Location of Well UNIT LETTER P, 990 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 18S RANGE 26E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3370 KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work was performed as follows on the Plugging and Abandonment of this well:
(1) Pulled tubing and packer (2) Ran tubing to 8800' and loaded casing with 9# mud (3) Spotted 35 sx cement plug from 8800' back to 8350', spotted 35 sx plug from 5800 back to 5350'. Pulled tubing, ran free-point, cut off and pulled 4½" casing from 4108' (4) Ran tubing and spotted 35 sacks plug at 4100', spotted 35 sx plug at 2200', spotted 35 sx plug at 1260' in and out of 8 5/8" casing, spotted 35 sx plug at 680' inside 8 5/8" casing. Erected and cemented 4½" x 4' marker, cut off dead men, cleaned location. P & A job ready for inspection.

RECEIVED

DEC 17 1968

O. C. C.
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Paul White</u>	TITLE <u>Engineer</u>	DATE <u>12-16-68</u>
APPROVED BY <u>R. F. Stamp</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u></u>

CONDITIONS OF APPROVAL, IF ANY: