

NEW MEXICO OIL CONSERVATION COMMISSION
DRAWER DD
ARTESIA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

Operator <i>Mountain Top</i>		Lease <i>Alamo State</i>		Well # <i>1</i>	
Location of Well	Unit/ <i>San Juan</i>	Section <i>16</i>	Township <i>18</i>	Range <i>25</i>	County <i>San Juan</i>
Drilling Contractor <i>Penetration Drilling</i>	Type of Equipment <i>Rotary</i>				
APPROVED CASING PROGRAM <i>100% approved 7-15-66 to 8-10-66</i>					
Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
<i>6 3/4</i>	<i>7 1/2</i>	<i>9.5</i>		<i>1084</i>	<i>100</i>

Casing Data: *27* *7 1/2* *20#* *J API New*

Surface *41* joints of *4 1/2* inch *9.5* # Grade *J-S API C 74J*

New (Approved) (~~Rejected~~)

Inspected by *Gressett* date *8-10-66*

Cementing Program

Size of hole *6 3/4* Size of Casing _____ Sacks cement required _____

Type of Shoe used _____ Float collar used _____ Btm 3 jts welded _____

TD of hole _____ Set _____ Feet of _____ Inch _____ # Grade _____

New-used csg. @ _____ with _____ sacks neat cement around shoe

+ _____ sax _____ additives _____

Plug down @ _____ (AM) (PM) Date _____

Cement circulated _____ No. of Sacks _____

Cemented by _____ Witnessed by _____

Temp. Survey ran @ _____ (AM) (PM) Date _____ Top cement @ _____

Casing test @ _____ (AM) (PM) Date _____

Method Used _____ Witnessed by _____

Checked for shut off @ _____ (AM) (PM) Date _____

Method used _____ Witnessed by _____

Remarks: *Plugging 6 3/4 hole to 1084, 8 3/4 hole to 808. Hole caving so badly could not run pipe or get back to TD. Spot 25 SX at 772' 8-20-66. Set bridge plug at 760' after first spot 35 sat @ 676' + 25 sat @ 576' 8-20-66 3:15 PM.*