

| | |
|------------------------|----|
| NO. OF COPIES RECEIVED | 5 |
| DISTRIBUTION | |
| SANTA FE | 1 |
| FILE | 1- |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | 3 |

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

MAY 21 1968

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease |
| State <input type="checkbox"/> Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Yates Petroleum Corporation | 8. Farm or Lease Name Nickson "EM" |
| 3. Address of Operator 207 So. 4th St. - Artesia, New Mexico | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER M 990 FEET FROM THE South LINE AND 950 FEET FROM West Lot 4 30 TOWNSHIP 18S RANGE 26E NMPM. | 10. Field and Pool, or Wildcat Yates Petroleum Corp. Draw S.A. 10000 |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3448' GR | 12. County Eddy |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☒
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 7-7/8" hole to 3419'. Ran Sidewall Neutron - Gamma Ray, Induction ES logs. Ran 106 jts of New J-55 SS 8RD 15.5# ST&C 5 1/2" OD casing to 3418'. Cemented with 600 sacks of Incor with 2% gel added. Plug down at 4:00 P.M. 5-19-68. Ran Temperature Survey after 15 hours. Top of cement inside 5 1/2" casing at 3410'. Behind 5 1/2" casing 420' from surface. Moving Rotary Rig.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul White TITLE Engineer DATE 5-20-68

APPROVED BY W. A. Gressett TITLE WARRANTY INSPECTOR DATE MAY 21 1968

CONDITIONS OF APPROVAL, IF ANY: