

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-056014

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. ☐ OIL
WELL ☐ GAS
WELL ☐ OTHER **WIW**

RECEIVED

2. NAME OF OPERATOR

NEWMONT OIL COMPANY

OCT 10 1978

3. ADDRESS OF OPERATOR

P.O. Box 1305, Artesia, New Mexico 88210

O.C.C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

ARTESIA, OFFICE

7. UNIT AGREEMENT NAME

West Loco Hills Grb #4 Sd Ut.

8. FARM OR LEASE NAME

Tract 8B

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Loco Hills (Q.G.SA)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 15, T18S, R29E NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3498' GLM

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

Locate Water Source

XXX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

10-2-78 -- A water leak of 86 BWPD from the casing head. We have shut this well in to see if the flow decreases. We request permission to monitor and test this well back flowing into a pit that will be maintained in a fenced and dried up manner. The District Engineer will be notified of our plans before the leak is repaired.

RECEIVED
OCT 4 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Office Manager

DATE

October 3, 1978

(This space for Federal or State office use)

APPROVED BY

TITLE

ACTING DISTRICT ENGINEER

DATE

OCT - 6 1978

CONDITIONS OF APPROVAL, IF ANY: