

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
verse side)B-
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 028990 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th Street - Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

NW NW 660' FNL & 990' FWL Sec. 25-18S-30E

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Creek "AL"

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Shugart

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREASec. 25-18S-30E
Unit D NMPM

12. COUNTY OR PARISH

Eddy

13. STATE

N.Mex.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3500 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☐

(Other)

5 1/2" csg. and perforate

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-11-70 - TD 3286'. Drilled 8" hole to 3286', ran 3286' of 5 1/2" 14# J-55 casing w/1-float shoe, set at 3286' and cemented with 500 sx. Cemented 1st 400 sx, mixed w/4% gel, last 100 sx Incor Neat. Cement did not circulate. PD 3:00 PM 2-11-70. Ran Temperature Survey - top of cmt. 150' from surface. Witness by Mr. Sanderson with USGS.

2-16-70 - Perf. with 40 - .471 Dresser Atlas bullets. 3172-3178, 3184-3190, 3232-3240.
Sand Frac'd down casing thru perforations with 1500 gallons acid w/25 RCN balls, 50000# 20-40 sand and 60000 gallons of water.

RECEIVED

FEB 25 1970

O. C. C.
ARTESIA, OFFICERECEIVED
FEB 24 1970
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Geologist

DATE

2-24-70

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL:

TITLE

DATE

ACCEPTED FOR RECORD PURPOSES
FEB 24 1970
Date ACTING District Engineer

*See Instructions on Reverse Side