

copy to SF.

Form 9-331  
(May 1963)

N. M. O. C. C. COPY

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

LC-028990 (B)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR  
**Yates Petroleum Corporation**

3. ADDRESS OF OPERATOR  
**207 So. Fourth, Artesia, New Mexico 88210**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

**NW NW, 660' FNL 990' FWL**

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
**3500 gr.**

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

**Creek AL**

9. WELL NO.

**6**

10. FIELD AND POOL, OR WILDCAT

**Shugart**

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

**Sec. 25-18S-30E**

12. COUNTY OR PARISH 13. STATE  
**Eddy N.M.**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

PULL OR ALTER CASING

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

**Deepening**

**X**

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well was deepened from 3286 to 3578 and logged on 12-6-70.

Broke down formation with straddle packers at 3504-44' w/500g. RA, at 3424-64' w/500g. RA.

On 12-9-70 attempted to sand frac selectively, communicated, frac'd open hole pay w/16700# 20/40 sand in 2000 bbls treated water at 18 BPM and 2200# down 3" tbg, ISIP - 100#, 6 min SIP - 950#.

Put well back on pump.

On 12-15-70 pumping 78 BOPD and 30 BLW.

RECEIVED  
DEC 15 1970  
U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE **XXXXXXXXXX** Owner

DATE **12/15/70**

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

ACCEPTED FOR RECORD PURPOSES  
DEC 16 1970

ACTING

District Engineer

\*See Instructions on Reverse Side

DEC 17 1970

O. C. C.  
ARTESIA, N.M.