

GEOLOGICAL SURVEY MOCC COPY
WELL STATUS REPORT

33 18S 30E

Footings Location of Well:

660 feet from East line
990 feet from South line

Pool

North Benson Queen

COUNTY

STATE

Eddy

NM

(To be submitted in quintuplicate on all inactive wells)

NAME AND ADDRESS OF OPERATOR

H & S Oil Company 216 American Home Building Artesia, NM 88210

WELL NO. AND LEASE NAME

McClay Federal #8

LEASE NO.

LCO28978(b)

1. When Was Well Shut-in or Last Produced? RECEIVED

1976

JUN 15 1977

2. Type Well

☐ Oil Well ☐ Gas Well ☒ Temp. Well ☐ C.C. Well

3. Producing Capability

BOPD 13 MCFGPD

BWPD 10 Date Last Tested 1976

4. Is Well Considered Capable of Production in Paying Quantities?

☒ Yes

☐ No

5. If Capable of Producing in Paying Quantities, Give Reasons For Not Producing Well.

RECEIVED

JUN 14 1977

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

6. If Not Capable of Producing in Paying Quantities, Give Reasons For Not Plugging Well At This Time.

Well is adjacent to a waterflood project, and indications are now showing that flood pressure is rocking the well bore.

7. What Are Future Plans For Operating Well (Include Estimated Dates)?

When flood pressures are evident then well will be re-treated and placed on production if well is capable of producing in paying quantities.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE June 10, 1977

(This space for Federal or State office use)

APPROVED BY

TITLE ACTING DISTRICT ENGINEER

DATE JUN 14 1977

CONDITIONS OF APPROVAL, IF ANY:

UNLESS FURTHER APPROVED, WELL MUST
BE PUT TO BENEFICIAL USE OR PLUGGED BY
APRIL OCTOBER

OCT 1977

THE
LIBRARY
OF THE
UNITED STATES
DEPARTMENT OF
THE ARMY
WASHINGTON, D. C. 20315

2025 RELEASE

100-101000-100-100

100-101000-100-100

100-101000-100-100

100-101000-100-100

100-101000-100-100

100-101000-100-100

100-101000-100-100