Form 9-331 (May 1963) Form approved. Budget Bureau No. 42-R1424. SUBMIT IN TRI 'ATE DEPARTMENT OF THE INTERIOR Other Instruction (Other Instruction) 5. LEASE DESIGNATION AND SERIAL NO. LC 028990 (b) GEOLOGICAL SURVEY 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME OTHER 2. NAME OF OPERATOR 8. FARM OR LEASE NAME Creek "AL" Yates Petroleum Corporation 3. ADDRESS OF OPERATOR 9. WELL NO. 207 South 4th Street - Artesia, New Mexico 88210 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT Shugart Markline SE-SW SW 330' FSL & 990' FWL of Sec. 24-18S-30E 11. SEC., T., R., M., OR BEK. AND SURVEY OR AREA Sec. 24-18S-30E Unit M NMPM 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH 13. STATE 3507' GR Eddy N.Mex. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF : TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF - REPAIRING WELL MULTIPLE COMPLETE FRACTURE TREAT FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING BANDONMENT* (Other) Spud & Set 8-5/8" csg. REPAIR WELL CHANGE PLANS (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-2-21-70 -Spudded 9:00 PM 2-21-70. 3-1-70 -Ran 729' of 8 5/8" casing, 1-Tex. Pattern Shoe, set at 729' and cemented with 200 sx of Incor. - 20 sx of gel, 100 sx 4% gel and 100 sx of Neat. Cement circulated to surface. Plug Down 6:00 PM 3-1-70. WOC 36 hours and drilled plug. Tested for 1 hr and bailed hole dry. Reduced hole to 8" and resumed drilling. RECEIVED