N. M. O. C. C. COPY

SUBMIT IN TRIPLICATE* (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424.

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO. LC-065478(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. Drilling

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR: PAN AMERICAN PETROLEUM CORPORATION

8. FARM OR LEASE NAME: DALCO "K" Federal

3. ADDRESS OF OPERATOR: BOX 68, HOBBS, N. M. 88240

9. WELL NO. 5

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface

10. FIELD AND POOL, OR WILDCAT: Empire Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

2310' FSL & 1335.4' FEL Sec. 3 (Unit O, SW/4 SE/4)

3-18-27 NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3606' R.D.B.

12. COUNTY OR PARISH: EDDY

13. STATE: N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐	WATER SHUT-OFF	☒	REPAIRING WELL	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐	FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐	SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
REPAIR WELL	☐	CHANGE PLANS	☐	(Other) Drilling	☒		
(Other)							

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus Drlg Co. spudded 11" hole 1:00 PM, 6-12-70. On 6-14-70, 8 5/8" OD 24# J-55 casing was set @ 1455' w/ 500 sx Incor 2% Gel + plain mix. Cmnt circ. After W.O.C. 12 hours, tested casing w/ 1500 PSI for 30 min. Test O.K.

Reduced hole to 7 7/8" @ 1455' and resumed drilling.

RECEIVED
JUN 29 1970
O. C. C.
ARTESIA, OFFICE

RECEIVED
JUN 25 1970
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED ______ TITLE AREA SUPERINTENDENT DATE ______

(This space for Federal or State office use)

APPROVED BY ______ TITLE ______ DATE ______

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD PURPOSES
JUN 26 1970
Date
ACTING District Engineer

*See Instructions on Reverse Side