

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-065478 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR
BOX 68, HOBBS, N. M. 83240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)
3508' R. DB

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
MALCO K Federal

9. WELL NO.
3

10. FIELD AND POOL, OR WILDCAT
EMPIRE A80

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
9-18-27 NMPM

12. COUNTY OR PARISH
EDDY

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING / ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

On 7-3-70. 4 1/2" OD 9.5" J-55 casing was set @ 5950' w/ 300 #4 Incon
neat + 1% CFR-2. Tested casing w/ 2000 psi for 30 min. Test O.K.
After WOC appx 48 hrs. perforated 586' B4' w/ 215 PF.
On 7-4-70 w/ 2600 gal 15%; 5000 gal Belled mine; 10,000 gal
24% STNE & 10,000 gal 3% overflush.
Evaluated -

On PT, pumped 24 hrs, 163 BO + 50 BLW. Gr. 44°. CPC 890

RECEIVED

JUL 17 1970

O. C. C.

ARTESIA, OFFICE

RECEIVED

JUL 16 1970

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE 7-15-70

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

O-4- USGS-ART

1- PCJ

ACCEPTED FOR RECORD PURPOSES

JUL 16 1970

Date

ACTING

District Engineer

*See Instructions on Reverse Side