

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Drilling Well	5. LEASE DESIGNATION AND SERIAL NO. LC-029419(b)
2. NAME OF OPERATOR Skelly Oil Company	6. IF INDIAN, ELIOTTE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 1351, Midland, Texas 79701	7. UNIT AGREEMENT NAME Skelly Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1760' FNL and 660' FWL, Sec. 27-17S-31E	8. FARM OR LEASE NAME Skelly Unit
14. PERMIT NO.	9. WELL NO. 107
15. ELEVATIONS (Show whether DF, RT, GR, etc.) Unknown	10. FIELD AND POOL, OR WELDSAN Grayburg-Jackson
	11. SEC., T., R. & N. OR B.L. AND SURVEY OF AREA Sec. 27-17S-31E
	12. COUNTY OF PARISH 13. STATE Eddy New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data.

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) **Spud and set casing** ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and space pertinent to this work.)*

- 1) Spudded 11" hole at 11:00 A. M. March 31, 1971.
- 2) Drilled to 628'.
- 3) Set 24# 8R SS J-55 8-5/8" OD casing at 628' and cemented with 260 sacks Dowell's Class "C" cement, 2% Calcium Chloride and 1 lb. Celophane flakes per sack. Plug down at 10:55 P. M. March 31, 1971. Cement circulated to surface. WOC 24 hours. Tested 8-5/8" OD casing to 1500# for one hour.
- 4) Drilled out cement.

RECEIVED

APR 8 1971

O. C. C.
ARTESIA, OFFICE

RECEIVED

APR - 6 1971

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED (Signed) J. R. Aveni

TITLE Dist. Adm. Coordinator

DATE April 5, 1971

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR 7 1971

APR 7 1971

APR 7 1971

APR 7 1971

APR 7 1971

APR 7 1971

ACCEPTED FOR RECORD PURPOSES
APR 7 - 1971
Date
ACTING District Engineer

*See Instructions on Reverse Side

