

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-025605

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

None

7. UNIT AGREEMENT NAME

Scoggin Draw Deep Unit

8. FARM OR LEASE NAME

Scoggin Draw Deep Unit

9. WELL NO.

1-Y

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 31-18S-27E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐2. NAME OF OPERATOR
Read & Stevens, Inc. ✓3. ADDRESS OF OPERATOR
P.O. Box 2126, Roswell, New Mexico 882014. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2086' FEL & 766' FSL, Sec. 31-18S-27E, N.M.P.M.

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3276.4 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) surface casing ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 2:10 P.M. 5/26/71

Ran 11 jts. of 12 3/4" 33# csg. 348' set @ 330' RKB.

Cemented w/300 sacks Class C w/2% CaCl₂, 1/2# flo-seal per sack.

Cement circulated.

Plug down @ 9:30 A.M. 5/27/71

WOC 18 hrs.

Pressure test to 1500# for 30 minutes.

Test O.K.

RECEIVED

JUN 8 1971

D. C. E.
ARTESIA, OFFICERECEIVED
JUN 7 1971
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Vice-President

DATE June 1, 1971

(This space for Federal or State official use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ACCEPTED FOR FEDERAL RECORDS
District Engineer

RECEIVED
JUN 7 1961
FBI - NEW YORK
COMM 125 1151 PM