

NM OIL CONVE. COM. SECTION
DANIEL D.
Artesia, NM 88210

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
C/SF GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
well well

2. NAME OF OPERATOR

Amoco Production Company /

3. ADDRESS OF OPERATOR

P. O. Box 68, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1650' FNL x 1653' FWL, Unit F

AT TOP PROD. INTERVAL: Sec. 11, T-18-S, R-27-E

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

5. LEASE

LC-067858

6. IF INDIAN, ALLOTTEE OR TRIBAL **RECEIVED**

7. UNIT AGREEMENT NAME

MAY - 4 1982

8. FARM OR LEASE NAME

Malco "S" Federal **O. C. D.**

9. WELL NO.

ARTESIA, OFFICE

1

10. FIELD OR WILDCAT NAME

Scoggin Draw-Morrow Gas

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

11-18-27

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3587' RDB

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

APR 23 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in service unit 4-5-82. Swabbed 6 hrs. with initial fluid level 5000 ft. from surface. Final fluid level 9000 ft. from surface. Pumped 5500 gal XL-4 gel, 2750 gal CO2, and 2310# 20/40 sand. Pumped 2500 gal XL-4 gel, 1-1/4 gal CO2, and 2310# 20/40 sand. Flushed with 48 bbls 10# gel. Flow tested for 96 hrs. and flowed 12 BC, 12 BLW, 4 BW, and 3108 MCF. Returned well to production.

O+4-USGS, A 1-Hou 1-Susp 1-CLF

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Cathy L. Gorman TITLE Ast. Adm. Analyst DATE 4-19-82

APPROVED BY
CONDITIONS OF

ACCEPTED FOR RECORD

PETER W. CHESTER

MAY 3 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side