

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved,
Bureau of Reclamation, No. 42 12124.

5. LEASE DESIGNATION AND SURVEY NO.

LC 22-30 (1)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th Street-Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface 330' FSL & 330' FEL Sec. 23-18S-30E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3494' GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Creek "AL"

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Snugart

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 23-18S-30E

Unit 2 NMPM

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spud

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-17-72 - Spudded at 9:00 AM 11-17-72.

11-26-72 - TD 732'. Drilled a 13" hole to 732', ran 732' of 10-3/4" 30# J-55 casing, 1-Texas Pattern Shoe and cemented at 732' with 250 sacks of Incor 2% CaCl and 9 sacks of gel. Cement circulated. PD 5:00 P.P., 11-26-72. WOC 72 hours and bail tested hole for 1 hour. Tested dry. Reduced hole to 10" and resumed drilling.

RECEIVED

DEC-51972

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Eddy M. Lutz

TITLE

Engineer

DATE

12-5-72

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED

DEC 5 - 1972

K. L. BEEKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side