		_		,	~		
NO. OF COPIES RECEIVED	3		EIVED			Form C-103	
DISTRIBUTION			LIVED			Supersedes C•102 and C	
SANTA FE		NEW MEX	ICO OIL CONSE	RVATION COMMISS	ION	Effective 1-	
FILE		JANC	1973	•		Sec. When it	
U.S.G.S.	+		1010			5a. Indicate Typ	
LAND OFFICE	++	1.				State	Fee A
OPERATOR			C. <u>C</u> .			5. State Oil & C	Sas Lease No.
	J <u>#</u> I	ARTESIA	, DFFICE				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "TAPPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)							
1. OIL GAS WELL WEL		OTHER-				7. Unit Agreeme	ent Name
2. Name of Operator						8. Farm or Lea	
Yates Petroleum Corporation							"BI" Com
3. Address of Operator						9. Well No.	
207 South 4th Street - Artesia, NM 88210						2 10. Field and F	Pool, or Wildcat
UNIT LETTERA	600	J FEET FROM 1	he North	LINE AND 610	LA FEET FROM	"Atoka W	.(Morrow)
THE East	LINE, SECTION_	<u>    25     </u> tol	NNSHIP 185	RANGE251	<u>с                                    </u>		
		15. Elevatio	on (Show whether 3438	DF, RT, GR, etc.) GR		12. County Eddy	
16. NOTI		propriate Box 1 ENTION TO:	Fo Indicate N	ature of Notice, I		ner Data REPORT OF	
PERFORM REMEDIAL WORK	]	PLUG /	ND ABANDON	Remedial work		ALT	
TEMPORARILY ABANDON	]			COMMENCE DRILLING O	PNS.	PLUG	AND ABANDONMENT
PULL OR ALTER CASING	_	CHANG	E PLANS	CASING TEST AND CEME	NT JOB XX		- an 53
_				OTHER Direct	<u>zional Sr</u>	vy, Peri	SF X
OTHER							
17. Describe Proposed or C		(0)		ile and size partiport	datas including	estimated date (	of starting any proposed
work) SEE RULE 1103.							
Woll was d	rilled	to TD of 9	029', log	ged and dir	ectional	ly survey	yed.
Well was drilled to TD of 9029', logged and directionally surveyed. Bottom hole location at 7560 was 15' North 28' West of casing shoe,							
BOTTOM NOIE INCALLON AL 7500 Was is for an less of decisions and was tested at 08800-8875'.							
with 1/2-1 degree to TD. The Morrow "B" sand was tested at 8800-8875',							
flowed gas at 2# TP on 1/4" choke; tested again at 8855-8930', flowed gas							
at 4# TP on k" choke, recovered 90' muddy formation water. Well was plugged							
back to 7486' as approved by Mr. Bill Gressett NMOCC, Oil & Gas Inspector,							
with 65 sacks Class H cement at 9010-8800' and 175 sx Class H w/15% Sd &							
3/4% CFk-2 at 7800-7400', dressed to 7486' w/BH location at 17' North and							
3/4% CFR-2 at 7800-7400°, dressed to 7400° w/En rocation at 1° for an 8955'; 27' West of casing shoe. Well was directionally drilled to new TD of 8955';							
27' West of casing shoe. Well was directionally diffied to new 12 of 0500 , tested at 8883-8907', GTS in 32", TSTM, rec. 280' SGCM; tested 8886-8955;							
tested at	8883-89	10/1, GTS 1	n 32', 18	TM, IEC. 20		w Unabl	o to log open
GTS in 8",	$14 \pm TP$	on $\frac{1}{2}$ ck,	rec. 220	GCM & IIUU	· Fu. WC		e to log open
hole. Ran	1 4½" ca	sing as fo	ollows: H	loat shoe a	nd colla	r at 890	2', 9 jts 11.6
x 00 (2001	1) 62 i	ite 11.6# B	(-55 (2005	5 <b>')</b> . 193 its	10.5# K	-55 (666	b'), chitu with
100 cv Poz	zlito (	1 5% D60 &	0.2% D-65	5 followed b	y 150 sx	expandi	ng cement 0.2%
<b>- - - - - - - - - -</b>	1.00 AM	12 2 72 +	on of crat	- at 7960'.	WOC 120	hrs. 109	qea & perr.
	⊃ <u>∩1</u>	$\frac{1}{2}$ w/10 jet	-s ran 2'	' tba & set	packer_a	t 8850.	Sand Frac W/
7900# 20-2 BA Locatio			ads in 2: East.2	30 bbls trea	ted gel	wtr. No	Sand Frac W/ recovery.
18. I hereby certify that the	information a	bove is true and con	nplete to the best	of my knowledge and be	lief.		
Eldie h	1. hund	april		Engineer		DATE	1-9-73
		<del>  </del>					
1	7 4	the state	<b>A</b> 11	AND ORD INC.			AN 17 1973
APPROVED BY	4 2510	solur	TITLE VIL	AND GAS INSPECT		DATE	·/ ·
CONDITIONS OF APPROV	AL IF ANY	, <b>.</b>	1. 0 4	1391 must	be amende	ed by # A	rearing
Prior to P	robucin	g well a	when re-			<i>,</i>	
provent	0	,		391 must	. •		· • •