

A & A ENGINEERING SERVICE

P. O. BOX 3323

Midland, Texas 79701

BOTTOM HOLE PRESSURE REPORT

Operator Coquina Oil Corporation Lease Clancy Well No. 1
 Field West Atoka Reservoir Cisco Datum Mid Perfs.
 Test Date October 22, 1973 Well Status Shut In Hours Shut In 24:00
 Tubing 2 3/8" Depth 6946' End Packer 6884' S. N.
 Casing Depth Perf. 7030-7140' Total Depth PB 7310'

	Depth	Press. Lbs/Sq. In.	Δ Press.	Gradient Lbs/Ft.
Tubing Press. <u>1394# DWT</u>	Surface	1396		
Casing Press.	5000	1637	241	.048
Top of Fluid. <u>None</u>	6685	1717	80	.047
Top of Water. <u>None</u>	6885	1727	10	.050
Temp. @.....°F.....	7085	1737	10	.050
Elev. KB.....Gl.....	0	0		
Last Test Date.....	7085	1737	Mid Perfs.	.050
Press. Last Test. <u>1425#</u>				
Change. <u>± 312#</u> Per Day.....				
Inst. No. <u>23862-N</u> Cal. <u>73-2</u>				
Tested By. <u>Spruwell</u>				
Calcu. By. <u>Arnett</u>				
Prod. Index.....Bbls/day/lb.....				
Drop.....				
Cumulative prod.....				

Remarks: