	· -	·-	
NO. OF COPIES RECEIVED			
	RE	Form C-103 Supersedes Old	
DISTRIBUTION		C-102 and C-103	
SANIAFE	NEW MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-65
FILE /	11	5a. Indicate Type of Lease	
U.S.G.S.	JUN 1 1973		State XX Fee
LAND OFFICE	0. C. C.		5. State Oil & Gas Lease No.
OPERATOR		B-6846	
ARTESIA, OFFICE			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
OIL XX GAS WELL OTHER-			7. Unit Agreement Name
2. Name of Operator			WLH Grb #4S. Ut
Newmont Oil Company			Tract 39
3, Address of Operator			9. Well No.
P. O. Box 1305, Artesia, New Mexico 88210			6
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER 1 990 FEET FROM THE EAST LINE AND 23101 FEET FROM			'
UNIT LETTER	FEET FROM THE	LINE AND FEET FR	**************************************
South	2 189	2QF	
THE SOUTH LINE, SECTION	2 TOWNSHIP 18S	RANGE 27L NMF	** (
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
		530' GL	Eddy
NOTICE OF INT	ppropriate Box To Indicate N FENTION TO:		NT REPORT OF:
	السار]	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ASANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JQB XX	<u></u>
		OTHER	
OTHER			
	rations (Clearly state all pertinent deta	nils, and give pertinent dates, includi	ng estimated date of starting any proposed
work) SEE RULE 1103.			
4-24-73Ran 448.48' of 24# 8 5/8" new casing and cemented with 100 sacks Class "H" cement			
with 2% Calcium Chloride. Did not circulate. Shut in for 18 hrs.			
$4-25-73\ldots$ Pressured up to 1000# for 30 mins - no pressure loss.			
			
<u>4-28-73</u> Ran 2736' 4.	5#, 9.5# new casing wit	h guide shoe on bottom	, and automatic float valv
on top of bo	ttom jt. Ran centraliz	ers on 5 bottom collar	s. Cemented w/450 sacks
light cement (composed of 40% Class ''C'' cement and 60% Pozmix) containing 6% gel			
and 2% CaCl ₂ , slurry wt. 12.7#/gal, followed w/100 sacks Class ''H'' containing 3/4%			
friction producer, 5# salt and 10# No. 3 sand/sack, slurry wt. 16.2#/gal. Pumped			
plug down to	2713' GLM and shut wel	l in. Cement did not	circulate.
<u>4-29-73</u> Top of cemen	t by temperature survey	950'.	
4-30-73Checked PBTD	27071		
T-JU-/JCHECKEU FOID	2,01 .		
18. I hereby certify that the information a	bove is true and complete to the best of	of my knowledge and belief.	
SIGNED Charles Ci	5/31/73		
SIGNED I NOVE 18	TITLE	Dist. Supt.	DATE

DIL AND GAS INSPECTOS

MAY 3 1 1973