

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SEE INSTRUCTIONS
ON REVERSE SIDE

Form approved.
Budget Bureau No. 42-R1424.
LEASE DESIGNATION AND SERIAL NO.

LC 59954

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
NEWMONT OIL COMPANY

3. ADDRESS OF OPERATOR
P. O. BOX 1305, ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
330' FSL & 330' FEL Section 9, T-18S, R-29E

7. UNIT AGREEMENT NAME
WEST LOCO HILLS #4 S. Ut.

8. FARM OR LEASE NAME
Tract 12

9. WELL NO.
5

10. FIELD AND POOL, OR WILDCAT
LOCO HILLS Q. GRB. S. A.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SEC. 9-18S-29E NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3494 GR

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	Check Water Flow		XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11/15/78---A water leak has developed from the braden head. We are draining this water into a pit from which it will be hauled back to the injection plant. The present rate of back flow is 99 BWPD. We request permission to continue this operation until the water source is located. The District Engineer will be notified of our plans before the leak is repaired.

18. I hereby certify that the foregoing is true and correct

SIGNED Rafael L. Lara

TITLE PRO. Engineer

DATE 11-15-78

(This space for Federal or State office use)

APPROVED BY José A. Lara

TITLE ACTING DISTRICT ENGINEER

DATE NOV 17 1978

CONDITIONS OF APPROVAL, IF ANY: