

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TR  
(Other instruct.  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 02426

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

NEWMONT OIL COMPANY ✓

NOV - 9 1973

3. ADDRESS OF OPERATOR

P. O. BOX 1305, ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

880' FSL & 1480' FEL Section 9, T-18S, R-29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3489 G.L.

7. UNIT AGREEMENT NAME

W.L.H.G. NO. 454 UT.

8. FARM OR LEASE NAME

Tract 19A

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Loco Hills

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 9-18S-R29E NMPM

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☒  
☐  
☐

REPAIRING WELL

☐  
☐  
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

11-4-73: Ran 323' of 8 5/8" 24# casing with Texas Pattern Shoe set at 325' GLM. Cemented w/150 sacks Class "H" cement containing 2% calcium chloride. Slurry weight 15.6#/gal. Wooden plug was used and displaced to 293' GLM.

11-5-73: After 23 hours setting time csg was pressure tested at 600 lbs for 30 minutes, no pressure drop, resumed drilling.

RECEIVED  
NOV 8 1973  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles C Joy

TITLE

District Superintendent

DATE

11/5/73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED  
NOV 8 - 1973  
H. L. BECKWITH  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side