

Details of bop test



Kewanee Oil Company

Feathers #1

10/15/74

Contractor: Hondo Drlg. Rig 8

Test by Yellow Jacket Tools and Services, Inc.



The above is a transposition of the pressure recorder charts covering test to the blowout control equipment in service on your well drilling in the Artesia Area, Artesia District, New Mexico. Test was made with test plug landed in casing head with the following test results:

Arrived location - rig coming out of hole.

Waiting on rig.