NO. OF COPIES RECEIVED	3	
DISTRIBUTION		
SANTA FE	ΠI	
FILE	I_L	1
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

Form C-103

DISTRIBUTI	ON	\preceq_{T}							Supersedes		
SANTA FE		7	 	NEW MEXICO O	IL CONS	ERVATION O	OMATS STON	EIVE	DEffective 1	C-103 -1-65	
FILE		1 5							-		
U.S.G.S.							1111 1	C 1074	Sa. Indicate Ty	rpe of Lease	
LAND OFFICE							JUL 1	6 1975	L	Fe	<u>. []</u>
OPERATOR		1]							Gas Lease No.	_
··								C. C.	E-2211	<i></i>	~~~
(DO HOT US	E THIS FOR	SUN	PROPOSALS TO DE	ES AND REPO	I OR PLUG BA	CK TO A DIFFER	ARTES!	A, OFFIC			.////
1.	USE "	APPLI	ICATION FOR PERM	IT -" (FORM C-10	I) FOR SUC	PROPOSALS.)			7. Unit Agreen	ent Name	7777
WELL X	GAS WELL		OTHER-								
2. Name of Operator	r				-				8. Form or Lea	ise Name	
Harvey	E. Yate	es C	Company, Ir	nc.					State		
3, Address of Oper				3 6 1: 63 1		77 1			9. Well No.	₩	
		urit	ty Nationa	l Bank Bldg	J., Ros	well, New	/ Nexico		# 3		
4. Location of Well	Λ.		220		Month		990	1/1/2	• •	Pool, or Wildcat	
UNIT LETTER	A	 _	330	EET FROM THE	HOTUI	LINE AND	990	FEET FROM	n. Benson	Oueen Gra	ZZZZZ
F	ast		32	TOWNSHIP	185		30E				11111
THE	LII	HE, 85	ECTION	TOWNSHIP.	100	MANGE	JOL.	кмРм.			/////
mmm	mn	m	i allilli	5. Elevation (Sho	w whether	DF, RT, GR, e	IC.)		12. County	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	444
		III		3425' GF					Eddy		
16.	*****	Chec	ck Appropria	te Box To Inc	dicate N	ature of No	tice. Repo	ort or Orl	er Data		
			FINTENTION			-1.00 01 110	_		REPORT O	F: •	
PERFORM REMEDIAL	. work 🔲			PLUG AND ABA	NDON	REMEDIAL WO	RK		ALT	ERING CASING	
TEMPORARILY ASAN	оон 🔲					COMMENCE DR				S AND ABANDORMS	ENT
PULL OR ALTER CAS	11NO			CHANGE PLANS	' 니	CARING TEST	HE CEMENT JO	e Man	ting surfa	co cacina	
					[]	OTHER	tunning t	Conch	cing sarra	ce cas mg	
OTKER											
17, Describe Propo		plete	d Operations (Cl	early state all pe	rtinent deta	ils, and give p	ertinent date	, including	estimated date	of starting any p	roposed
work) SEE AU	LE 1103.										
2 20 75	Coudd	۱ ا	1011								
3 - 28 - 75	Spudue	eu v	1011								
6-04-75	Ran 60	731	8 5/8" 32:	# 8 rd. t hd.	casin	a circul	atod wit	-h 150 d	sacks como	n+	
			0 0/0 02/	, or as una.	Cusin	g, Circui	acca wii	JI 130 :	sacks ceme	116.	
	Drille	ed c	out cement	, bailed ho	ole dry	. Tested	12 hrs.	no wate	er.		
					•		•				
						•					
						,					
	•						· • • •				
							•				
			g after the								
18. I hereby certify	that the le	orma	Mion above is tru	se and complete to	the best o	f my knowledge	e and belief.				
\bigcirc	ned.	l	1.t.			V. P			_	77	
SISHED		-//	1003	т	11TLE	· / ·			DATE	-11-75	
) D	E-14	ويستها البراقي والمراباة والتبريدات							Maria Santa
	or Recor	ra (U	A CONTRACTOR	/		SUPERVISO	R, DISTRI	CT II	.11	IL 17197	5
APPROVED BY	-,01,	1	- water	Y	1768	, , , , , , , , , , , , , , , , , , ,			- DATE	1 10/ 5	

A The Control of the	