

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate (Other instructions on reverse side)

Form approved,
Budget Bureau No. 42-11424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

- | | | |
|---|--|--|
| 1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ | | 7. UNIT AGREEMENT NAME |
| 2. NAME OF OPERATOR
Yates Petroleum Corporation | | 8. FARM OR LEASE NAME
Federal "EF" Com. |
| 3. ADDRESS OF OPERATOR
207 South 4th Street-Artesia, NM 88210 | | 9. WELL NO.
1 |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 660' FSL & 1980' FEL of Sec. 6-18S-25E | | 10. FIELD AND POOL, OR WILDCAT
Richard Knob |
| 14. PERMIT NO. | | 11. SEC., T., R., M., OR FOLK, AND SURVEY OR AREA
Sec. 6-18S-25E
Unit 0 NMPM |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3632' GR | | 12. COUNTY OR PARISH
Eddy |
| | | 13. STATE
NM |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :

SUBSEQUENT REPORT OF :

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL.

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

SHOOTING OR ACIDIZING
(Other) Set 4¹

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 8413'; PBTD 8287'. Ran 258 joints of 4½" casing as follows: 48 joints 11.6# J-55 LT&C (1576'); 194 joints 10.5# J-55 LT&C (6205') and 16 joints 11.6# J-55 LT&C (522') (Total 8303') w/Guide shoe at 8320' and Float Collar at 8287'. Cemented w/500 gallons mud flush, 230 sacks Class "C" w/1/2% CFR-2 & 5# salt followed by 180 sacks of Halli-Lite and 150 sacks Class "H" w/1/2% CFR-2 and 5# KCL. Displaced w/40 bbls 2% KCL & 95 bbls fresh water. PD 2:00 AM 5-19-75, tested to 1800 psi. Tested OK. WOC 12 hours and ran temperature survey and found top of cement behind casing at 6020'.

RECEIVED

MAY 26 1975

G. C. C.
ARTESIA, OFFICE

RECEIVED

MAY - 3 1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true, and correct

SIGNED

TITLE

Engineer

DATE _____

5-21-75

(This space for Federal or State office use)

TITLE

DATE _____

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

***See Instructions on Reverse Side**