COPIES RECEIVED 3	AUG 1 1	
MELL GAS WELL X OTHE	ICES AND REPORTS ON WELLS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DECOMP PERMIT	7. Unit Agreement Name
Atlantic Richfield Company 3. V. iress of Operator P. O. Box 1710, Hobbs, New	· · · · · · · · · · · · · · · · · · ·	8. Farm or Lease Name Stirling Com 9. Well No.
4. Location of Well UNIT LETTER F 1650	FEET FROM THE North LINE AND 1980 FEE	1 10. Field and Pool, or Wildcat Red Lake Penn Gas
	Township 18S RANGE 27E 15. Elevation (Show whether DF, RT, CR, etc.) 3288' GR	I2. County Eddy
Check Approprior	riate Box To Indicate Nature of Notice, Report of Notice, SUBSEQ	
PERFORM REMEDIAL WORK	CHANGE PLANS CASING TEST AND CEMENT JOB	ALTERING CASING PLUG AND ABANDONMENT Csg & cmt, perf & treat [X]
OTHER		A cart, peri a creat A

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated do-e of starting any proposed work) SEE RULE 1103.

Drld 7-7/8" hole to 9072'. Tested Morrow 9035-9072' on 6/16/75. DST #1, opened tool @ 4:00 AM 6/16/75 for 20 mins preflow w/good blow. Closed tool for 1 hr SI. Opened tool $1\frac{1}{4}$ hr flow period w/strong blow through out, no gas to surface. Closed tool for 2 hr SI. POH w/tools, rec 60' drlg fluid. Btm ck, IHMP 4347, IFP 35, ISIP 803, FFP 53-70, FSIP 2342, FHMP 4329, Temp 148°. Top ck recorder failed. Sampler recovery: .095 cu ft gas @ 50#, 1400 cc drlg fluid. WIH w/7-7/8" bit, resumed drlg. Reached TD 9350' @ 11:10 AM 6/19/75. Circ 4 hrs & POH. Ran GR-CNL 0-9345', FDC 5800-9345', Dual LL w/caliper 1902-9344', MSF log 5800-9345'. Ran top to bottom, 5¹/₂" OD 17# N-80 csg (618') & 5¹/₂" OD 17# J-55 csg (4838") 5¹/₂" OD 15.5# J-55 csg (3877') w/FS & FC set @ 9350' & cmtd w/350 sx HLW w/3#/sk w/KCL, followed by 500 sx Cl H, .6% Halad 22 & 3#/sk w/KCL. Plug down w/2% KCL wtr w/l gal Marflo w/1000 gal & $\frac{1}{2}$ of 1% inhibitor, plug down w/2400#. JC @ 7:15 AM 6/21/75. Installed well head. WOC 9 hrs, ran temp survey, indicated TOC @ 5300' from surface. WOC 72 hrs. Pressure tested csg to 1000# for 30 mins, tested OK. PBD 9289'. Spotted 6 bbls 7¹/₂% MS acid 9174-8916'. Ran GR Corr log 9286-5800'. WIH w/tbg & pkr, set pkr @ 8903'. Displaced tbg w/35,000 ft³ N₂, perf'd 1 JS ea @ 9032, 35, 53, 56, 59, 92, 95, 9142, 44, 52, 54, 57, 60, 72 & 9174' = 15 holes. Opened to pit for 15 hrs, gas TSTM. pmpd 5000 ft³ N2 pad. Trtd perfs 9032-9174' w/4000 gals $7\frac{1}{2}\%$ MS acid, 96,000 ft³ N2 added. Flushed w/23 bbls KCL wtr w/23,000 ft3 N2 added. MP 7000#, Min 6400#, ISIP 3800#. 5 min SIP 3000#, 15 min SIP 2100#. Flwd to pit on 3/4" ck 17 hrs, TP 50#. Calculated flow 900 MCFGPD, no gauge of fluid. Trtd perfs 9032-9174' w/34,000# 40/60 sd in 28,644 (cont'd on attached Page #2)

18. I hereby certify that the information above is true and complete to the best of my sowie

		Dist. Drlg. Supv.	7/31/75
APPROVED BY U.U. Gressett TITLE SUPERVISOR, DISTRICT II DATE DATE	APPROVED BY U. A. Gressett	SUPERVISOR, DISTRICT II	AUG 4 1975