

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND	FILE
OPER	OR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-101
Effective 1-1-67

RECEIVED

SUNDY NOTICES AND REPORTS ON WELLS SEP 25 1975
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH OR USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	O. C. C. ARTESIA, OFFICE
2. Name of Operator Yates Petroleum Corporation	
3. Address of Operator 207 South 4th Street - Artesia, NM 88210	
4. Location of Well UNIT LETTER I 990 FEET FROM THE East LINE AND 2310 FEET FROM THE South LINE, SECTION 21 TOWNSHIP 18S RANGE 26E N.M.P.M.	

5. Indicate type of well a. <input type="checkbox"/> Oil <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Other
6. Unit Agreement Name
7. Unit Agreement No.
8. Field Name Dayton "ER"
9. Well No. 1
10. Field, Pool, or Well at Und. Atoka (S.A.)
11. County Eddy

15. Elevation (Show whether DF, RT, GP, etc.) 3363' GR
--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	STOPPING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	REPAIR ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT LOG <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, both for work and for completion of work) SEE RULE 1103.

9-22-75 - Spudded 15" hole at 4:00 PM 9-22-75.

TD 400' - Ran 10 jts 10-3/4" 41.85# 8R used casing (402') set at 400' KB and cemented w/250 sacks Class "C" 4% CaCl. PD 2:00 PM 9-23-75. Cement circulated. WOC 12 hours, backed off landing jt and RTH w/9 1/2" bit, drilled cement and resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie M. Halyard TITLE Engineer

9-24-75

APPROVED BY For Record Only TITLE SUPERVISOR, DISTRICT II

DATE SEP 25 1975

CONDITIONS OF APPROVAL, IF ANY: