

COPIES RECEIVED

DISTRIBUTION

SANTA FE

FILE

U.S.G.S.

1. END PICE

OPF OR

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

FEB 12 1976

Form O.C.C. 101
 2 pages less 1st
 C-101 and C-102
 Effective 1-1-76

SUNDRY NOTICES AND REPORTS OF WELLS **O. C. C.**
ARTESIA OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REFINISH OR REPAIR EXISTING WELLS. USE "APPLICATION FOR PERMIT TO DRILL OR REFINISH OR REPAIR EXISTING WELLS" FORM FOR SUCH PROPOSALS.)

1. ☒ GAS WELL ☐ OTHER

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
207 So. 4th Street - Artesia, NM 88210

4. Location of Well

UNIT LETTER **N** **330** FEET FROM THE **South** LINE AND **2310** FEET FROM THE **West** LINE, SECTION **21** TOWNSHIP **18S** RANGE **26E** RMPM.

5. Elevation (Show whether DF, RT, GR, etc.)
3400' GR

6. County
Eddy

7. Unit Agreement No.

8. Well No.
1

9. Field No. (Last, or without)
Und. Atoka (S.A.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPS. ☒

CASING TEST AND CEMENT JOBS ☒

OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data, in the work) SEE RULE 1103.

Spudded a 15" hole at 4:30 PM 1-29-76.

TD 385' - Ran 10 joints of 10-3/4" 32# used casing (392.75') set at 385' KB. Cemented by Denton w/200 sacks Class "C" 4% CaCl cement. Cement circulated. PD 2:00 AM 1-30-76. WOC 12 hours, drilled plug and reduced hole to 9 1/2" and resumed drilling.

TD 1220'. Ran 32 joints of 7" 20# K-55 (1231.58') of casing set at 1220'. 1-Tex Pattern Shoe, 2 centralizers at 1180 and 538' and baskets at 506 and 576'. Cemented by Denton w/350 sacks of Lite-wt 2% CaCl cement, followed w/150 sacks of Class "C" 2% CaCl. Cement did not circulate. WOC 6 hours and ran Temperature Survey, found top of cement at 460'. Ran 1" to 420' and spotted 50 sacks of Class "C" 4% CaCl w/full returns. Pulled 1" to 210', spotted 60 sacks of Class "C" 4% CaCl w/full returns. Pulled 1" to 42' and spotted 30 sacks of Class "C" 4% CaCl. Cement circulated. JC 8:00 PM 2-1-76. WOC 18 hours, backed off landing joint, nipples up and installed BOP's, tested to 1000#. OK. Drilled shoe and tested casing to 600#. OK. Reduced hole to 6 1/4" and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED Christine Johnson TITLE Geol. Secty

2-11-76

APPROVED BY W.A. Gussert TITLE SUPERVISOR, DISTRICT II

DATE FEB 12 1976

CONDITIONS OF APPROVAL, IF ANY: