

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPER. OR	

RECEIVED

FEB 17 1976

NEW MEXICO OIL CONSERVATION COMMISSION

Form O-103  
Revised 10/64  
O-102 and O-104  
Effective 1-1-67

O. C. C.  
ARTESIA, OFFICE

5. Estimate type of work	See <input checked="" type="checkbox"/>
6. Check for completion of work	

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG OR TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM (O-101) FOR SUCH PROPOSALS.)

1. Name of Operator Yates Petroleum Corporation ✓	2. Name of Well Dayton "FI"
3. Address of Operator 207 South 4th Street	4. Location of Well 1
5. Unit Letter A	6. Feet from the North Line and 960 Feet from East Line, Section 28 Township 18S Range 26E NMPM.
7. Elevation (Show whether DF, RT, GR, etc.) 3373' GR	8. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	FILE AND ADD ONALY <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated work) SEE RULE 1103.

Spudded a 15" hole at 7:00 PM 2-3-76.  
TD 376' - Ran 10 joints of 10-3/4" 32# used casing (382.94') set at 376' KB. Cemented by Denton w/200 sacks of Class "C" 4% CaCl. PD 5:00 AM 2-4-76. Cement circulated. WOC 21 hours. Drilled plug and reduced hole to 9 1/2" and resumed drilling.

TD 1230'. Ran 31 joints of new 7" 20# K-55 ST&C casing, (1233.51') set at 1230'. Centralizers at 1205 and 561', baskets at 528 and 603'. Cemented by Denton w/350 sacks of 2% CaCl followed w/150 sacks of Class C 2% CaCl. PD 11:00 AM 2-6-76. Cement circulated. WOC 18 hours, nipples up, installed BOP's and tested to 1000#. OK. Drilled plug and tested casing to 600#. OK. Reduced hole to 6 1/4" and resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED <u>Christine Tomlinson</u>	TITLE <u>Geol. Secty</u>	DATE <u>2-16-76</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>SUPERVISOR, DISTRICT II</u>	DATE <u>FEB 17 1976</u>
CONDITIONS OF APPROVAL, IF ANY:		