NO. OF COPIES RECEIVED	Form C-103
DISTRIBUTION	Supersedes Old
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE , .	
U.S.G.S. RECEIVED	5a. Indicate Type of Lease
LAND OFFICE	State X Fee
OPERATOR 1070	5, State Oil & Gas Lease No.
APR - 1 1976	В 3823-1
SUNDRY NOTICES AND REPORTS ON WELLS TO NOT USE THIS FORM FOR PHOPOSALS TO DELLE OR TO BEEPEN OF PLUG BACK TO A DIFFERENT ESPAYOIR.  USE "AFFEICATION FOR PERMIT -" IFORM C-101) FOR SUCH PROPOSALS.	
1. ARTESIA, DEFICE  WELL X VELL OTHER-	7. Unit Agreement Name
2. Name of Operator  Atlantic Richfield Company	8. Form or Lease Name Empire Abo Unit "I"
3. Address of Operator	9. Well No.
P. O. Box 1710, Hobbs, New Mexico 88240	3 271
4. Location of Well	10. Field and Pool, or Wilicat
UNIT LETTER B 1700 FEET FROM THE EAST LINE AND FEET FROM	Empire Abo
THE North Line, SECTION 5 TOWNSHIP 18S RANGE 28E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
	12. County
3654.0' GR	Eddy
Check Appropriate Box To Indicate Nature of Notice, Report or Other Notice of Intention to:  Perform remedial work  Temporarily Abandon  Commence Drilling Opns.	FREPORT OF:
PULL OR ALTER CASING CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
Rigged up Hondo Drlg Co. Rig #6, spudded 11" hole @ 10:30 AM 3/17/76 3/17/76. Ran 13 jts (522') of 8-5/8" OD 8rd 24# K-55 ST&C w/FC & FS, 451'. Cmtd csg w/100 sx Cl C cont'g 4% gel & 6# salt/sk followed by PD @ 12:20 AM 3/18/76. WOC 4 hrs & ckd top of cmt @ 53' from surface to surface w/3½ yds Redi-mix. WOC 14 hrs. Surface csg was cmtd unde following criteria for cmtg under this option is submitted as follows 1. Volume of cmt slurry was 302 cu ft. Brand names, additives, perce of placement were used as shown above.  2. Approximate temperature of cmt slurry when mixed was 70°.  3. Estimated minimum formation temperature in zone of interest was 68 4. Estimate of cement strength @ time of casing test is 1400 PSI.  5. Actual time cement in place prior to commencing test was 14 hrs.  6. Pressure tested csg to 1000# for 30 mins. Tested OK. Resumed dri hole).	set csg @ 535', FC @ 100 sx Cl C w/2% CaCl Filled annulus 53' r OCC Option 2. The : nt additives & sequence