

Bennett Wire Line Service  
305 McArthur Ave. Ph. (505) 746 - 3281  
Artesia, New Mexico - 88210

## BOTTOM HOLE PRESSURE SURVEY REPORT

OPERATOR READ & STEVENS INC.  
LEASE Turkey Track Com.  
WELL NO. 1  
FIELD \_\_\_\_\_  
DATE 1/28/78 TIME \_\_\_\_\_  
STATUS Shut-in TEST DEPTH 10,970 Ft.  
TIME S.I. 24 Hrs. LAST TEST DATE \_\_\_\_\_  
CAS. PRES. \_\_\_\_\_ BHP LAST TEST \_\_\_\_\_  
TUB. PRES. 3278 Lbs. BHP CHANGE \_\_\_\_\_  
ELEV. \_\_\_\_\_ FLUID TOP 10,000 Ft.  
DATUM \_\_\_\_\_ WATER TOP \_\_\_\_\_  
TEMP 172 ° RUN BY Bennett  
CLOCK NO. \_\_\_\_\_ GAUGE NO. \_\_\_\_\_  
ELEMENT NO. 9526

| DEPTH   | PRESSURE  | GRADIENT<br>Lbs./100 Ft. |
|---------|-----------|--------------------------|
| 0 Ft.   | 3278 Lbs. |                          |
| 5000 "  | 3738 "    | 9.2                      |
| 10000 " | 4213 "    | 9.5                      |
| 10970 " | 4413 "    | 20.6                     |

