

Form 9-331  
Dec. 1973

MAR 3 1980

Form Approved.  
Budget Bureau No. 42-R1424

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

O. C. D.  
ARTESIA, OFFICE

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill on a deep or shallow well in a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well    gas ☒ well    other ☐    **FEB 27 1980**

2. NAME OF OPERATOR  
Amoco Production Company

3. ADDRESS OF OPERATOR  
P. O. Box 68, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1980' FNL x 1650' FEL, Sec. 3  
AT SURFACE: (Unit G, SW/4 SE/4)  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) _____	

5. LEASE  
LC-065478-b

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Federal F Gas Com.

9. WELL NO.  
1

10. FIELD OR WILDCAT NAME  
Und. Scoggin Draw Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
3-18-27

12. COUNTY OR PARISH  
Eddy

13. STATE  
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3560.1 GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Moved in service unit 2-13-80. Tested casing with 1000# for 30 min. Test OK. Perforated 9691'-9704' with 4 JSPF. Ran tubing, packer, and tailpipe. Packer set at 9475'. Tailpipe at 9538'. Acidized with 3000 gal 7-1/2% MSA acid. Flushed with 41 bbls 4% KCL water. Currently swab testing.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Bob Davis TITLE Assist. Admin. Ana DATE 2-25-80

(Orig. Sgd.) GEORGE H. STEWART (This space for Federal or State office use)  
ACTING DISTRICT ENGINEER

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE FEB 28 1980  
CONDITIONS OF APPROVAL, IF ANY:

0+4 USGS-A, 1-Hou, 1-Susp, 1-BD, 1-Hondo