N OF COPIES RECEIVE	160		<u> </u>							Form C-10:	3		
DISTRIBUTION								0 = 6		Supersedes C-102 and			
SANTA FE		$\angle$		N	EW MEX	ICO OIL CO	ONS	ERVATION COMMISS	idF   V E	D Effective			
FILE		$\angle$											
U.S.G.S.	-							NOV	- 6 1978	5a. Indicate T			
LAND OFFICE									0 13/6	State	Fee XX		
OPERATOR								n	C 0	5. State Oil 6	Gas Lease No.		
	··-							L). Rater	C. C.				
		SUN	IDRY NO	TICES	AND R	EPORTS	ON	WELLS	- CAPICE				
(00 NOT USE T	HIS FOR	APP	ICATION FOR	PERMIT	- " (FORK	A C-1011 FOR	SUC	ACK TO A DIFFERENT RESI H PROPOSALS.	ERVOIR.				
!. oir [_]	645	<u></u> 3								7. Unit Agreen	ient Name		
werr	WELL		ОТ	HER-									
Name of € perator										8. Farm or Lease Name			
Harvey E. Yates Company 🗸											Loco Hills Welch		
, Address of Operator											9. Well No.		
P. O. Box 1933, Roswell, N. M. 88201											1		
i, Location of Well										1	Pool, or Wildcat		
UNIT LETTER	D		480	FEE	T FROM TE	Nort	h	LINE AND	FEET FROM	Und. So.	Empire Morrow		
THE West	LII	NE, 51	ECTION	9	Tow	NSHIP 1	8S	RANGE 29E					
		• • • •	*****	<del></del>						VIIIIII			
		111;	111111	)) 15.	Elevation	1 (Show whet	ther	DF, RT, GR, etc.)		12. County			
	77777	777,	711111	77		<u>3516'</u>				Eddy			
, t.,	(	Chec	ck Appro	priate	Box T	o Indicat	e N	lature of Notice, R	Report or Ot	her Data			
N			F INTEN						-	T REPORT O	F:		
PERFORM REMEDIAL WO	A K				PLUG AN	HODHABA DI		REMEDIAL WORK		ALT	ERING CASING		
TEMPORARILY ABANDON								COMMENCE DRILLING OF	'NS.	PLU	G AND ABANDONMENT		
PULL OR ALTER CASING					CHANGE	PLANS		CASING TEST AND CEME					
						_		OTHER Run pro	d. casing	, cement,	etc. KX		
OTHER							┙,						
2. Descript Learned	or Com	معمام	d Operation	a (Class	+1	-11	dat	ails, and give pertinent o	d-+ il-li		6 . 5		
work) SEE RULE	1103.	prete	a Operation	S (Crea	ry state t	in periment	aei	itis, and give pertinent i	iates, including	g estimated date (	ij starting any proposed		
0 20 70	n	2.7		/1:	1 170	/O1> =	1/0	W OD 17# 7 00	000 7000	•			
9-30-78								2" OD 17# L-80	8RD LT&C	casing set	at		
	11,	199	• 14 KB	and	cemen	ted as	101	LIOWS:					
	1	Cti	roulete	a bo	10/-	i ~ nmn	£,	m 60 minutas					
		1. Circulated hole w/rig pump for 60 minutes.											
	2. Pumped 1000 gals Mud Flush.												
	<ul> <li>3. 10 Bbls. fresh water.</li> <li>4. 375 Sx Halliburton LW w/5/10% Halad 22 &amp; 3# KCL/Sx and 350 Sx Class F</li> </ul>										Class U		
	4. 3/3 SX Halliburton LW W/3/10% Halad 22 & 3# KCL/SX and 350 SX Class H W/ $3/10\%$ CFR-2 & 5# KCL/Sx.										Class II		
		<ul><li>5. Dropped plug and displaced w/259 Bbls fresh water w/1800 psi.</li><li>6. Bumped plug w/2600 psi @ 11:45 pm 9-30-78.</li></ul>											
		7. Released pressure. Float held OK.											
	The BOP was raised and 5 1/2" casing slips set. Rig release									esed @ 4.	00 am -		
	10-1-78.									.casca e 4.	oo am		
	10	- '	•										
10-1-78	TOC	760	10.1										
10-1-70	100	, 00											
_			1										
i". I hereby consisty the	t the in	forme	tion bove	is true	and compl	ete to the be	est (	of my knowledge and bel	ief.				
11	1		1/2	1									
Jenes Ter	K	/(	TARI	ll		T17. 5		Engineer		DATE 11	-3-78		
						11161							

NOV - 7 1978